

Service Repair Sheet 68923

Contact Name

Abbey McAnaney

Company/ Hospital Name

Vet Direct Services Ltd

Position

Technical Support RVN

Direct Phone

01912642705

General Phone

01912642705

Opera Account

00012824

Email

tech@vet-direct.com

Date Received

07/Oct/2024

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37126	0111275	A106337	Oxygen Analyser	Complete - Repaired Time :0 Hour(s)

Device was reading 86.7% in air and couldn't be adjusted lower.

I have performed a reset and recentred the device on 20.9%

Repair	Ref	S/N	Equipment Type	
SRN37127	0110660	A111126	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The sensor is within spec. No fault found.