Service Repair Sheet 68830

Contact Name

Company/ Hospital Name

Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By

Vincent Wu

Hui-Li Medical Equipment Limited

0088 634 910790 +886 34910790

00006036

vince.wu@huilimedical.com

paid by Square 09/Jul/2024 Robert Connor

Repair SRN36526 Ref

S/N 4410520 70740154 **Equipment Type** Capnograph

Complete - Repaired Time: 0.5 Hour(s)

Parts Replaced

Qty: 1 4420504 Qty: 1 4430610

The Capnograph VM 2500-S has been repaired. The ISA module has been replaced. The case has been replaced to use the new PSU. A new PSU has been supplied with US and UK adapters.