



Service Repair Sheet SRS68905

Contact Name Radeet Kabir
 Company/ Hospital Name Kings College Hospital (use this o
 Department
 Position
 Direct Phone 02032991607
 General Phone 02032997878
 Opera Account 00002990
 Email radeet.kabir@nhs.net
 Order Number
 Date Received 02/Oct/2024
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Quote

VIAMEDclean

Goods In Only

Decontamination
 certificate provided
 by customer ☒

Cleaned by Viamed,
 if no declaration certificate
 from customer ☒

Signed: RC
 Date: 2/10/24

Goods Out Only

Cleaned by Viamed before
 returning to customer

Signed: _____
 Date: _____

Notes 20/Sep/2024 Aqib Majeed

20/Sep/2024 Aqib Majeed

customer returning a mx300-i for repair, SN: 340518

02/Oct/2024 Robert Connor

Received 1 x MX300i s/n 340518, with coiled cable s/n 0010598, and R17MED s/n 151102, with flow diverter. Please remind
 customer that equipment must be returned with a declaration of decontamination status that has been filled in.

Ready For quote

CGNEON 10.10.24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37113	Oxygen Monitor	0111235	340518	N
SRN37114	Oxygen Sensor	0110017	151102	Yes
SRN37115	Misc. Cable	0131202	0010598	N

~~121208~~ x

0140005 x 1 @ 1/2hr @ £90 per hr

S/N, SRS, SRN

~~0140005~~ x

0121208 x 1 @ £5

SRS, SRN

UPS x 1 @ £12.