

Service Repair Sheet 68921

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Chantelle Louise Curry

Auto Trade Company

07564625494

07564625494

CID27563

autotrade01@outlook.com

09/Oct/2024

Robert Connor

Repair Ref S/N
SRN37128 0110122 136587

Equipment Type
Oxygen Sensor

Under Warranty

Parts Replaced

Time :0 Hour(s)

Qty: 1 0110122

Replaced under warranty with S/N 167276