Service Repair Sheet SRS68929

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received Booked in By

Main Company

Type Return

Ross Bowden

Cardiff and Vale UHB

Clinical Engineering

02921845678

02920903794

00000092

Ross.Bowden@wales.nhs.uk

15/Oct/2024

Robert Connor

Viamed

Quote



Notes require serv/calibration for V1000, s/n PR02450A13

require serv/calibration for V1000, s/n PR02450A13. Mentioned cert of decontamination and removal of batteries

Received 1 x V1000 s/n PR02450A13, with grey silicone cover and blue fabric carry case.

Ready For quote

CGreen 15-10-24

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
CDN27132	Foetal Simulator			

1480000 × 1 @ 660 S/N, SRS, SRN 1430309 × 1 FOC SRS, SRN × 1 E12.