

Service Repair Sheet SRS68905  
 Contact Name  
 Company/ Hospital Name  
 Department  
 Position  
 Direct Phone  
 General Phone  
 Opera Account  
 Email  
 Order Number  
 Date Received  
 Booked in By  
 Main Company  
 Type Return

Radeet Kabir  
 Kings College Hospital (use this o

02032991607  
 02032997878  
 00002990  
 radeet.kabir@nhs.net

02/Oct/2024  
 Robert Connor  
 Viamed  
 Quote

### VIAMEDclean

**Goods In Only**  
 Decontamination  
 certificate provided  
 by customer ☒

Cleaned by Viamed,  
 if no declaration certificate  
 from customer ☒  
 Signed: RC  
 Date: 2/10/24

### Goods Out Only

Cleaned by Viamed before  
 returning to customer  
 Signed: \_\_\_\_\_  
 Date: \_\_\_\_\_

Notes 20/Sep/2024 Aqib Majeed

20/Sep/2024 Aqib Majeed

customer returning a mx300-i for repair, SN: 340518

02/Oct/2024 Robert Connor

Received 1 x MX300i s/n 340518, with coiled cable s/n 0010598, and R17MED s/n 151102, with flow diverter. Please remind customer that equipment must be returned with a declaration of decontamination status that has been filled in.

Ready For quote

CGNEON 10.10.24

Repair Complete Signed

CGreen 25.10.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37113	Oxygen Monitor	0111235	340518	N
SRN37114	Oxygen Sensor	0110017	151102	Yes
SRN37115	Misc. Cable	0131202	0010598	N

- Part of unit.

~~121208 x 1~~

0140005 x 1 @ 1/2 hr @ £90 per hr £0 Quote

S/N, SRS, SRN

Repair declined.  
 customer requested  
 Disposal.

Declined.  
 cg. 25.24

~~0140005 x 1~~

0121208 x 1 @ £5 £0

SRS, SRN

Repair declined.  
 customer requested disposal

Please Add.

UPS x 1 @ £12. £0

0140011 x 1  
 S/N, SRS, SRN.  
 No fault found.