Service Repair Sheet SRS68922

Contact Name

Company/ Hospital Name

Department

Position

**Direct Phone** 

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company Type Return Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

21/Oct/2024

Robert Connor

Viamed

Warranty

Deconta	In Only mination te provided mer	9
	by Viamed, ration certificate mer	B

Cleaned by Viamed before returning to customer

Signed: Date:

Notes 07/Oct/2024 Kate Griffiths

07/Oct/2024 Kate Griffiths

2 x R-43v to return, s/n: S/N - V10151 and V101762, checking V10151 is correct as I am unable to find it on i/stats. Fault: "oxygen percentage is minus valve and calib. failed."

07/Oct/2024 Kate Griffiths

EDIT, the s/n is V101751

21/Oct/2024 Robert Connor

Received 2 x R-42V s/n V101751, V101762. Sensors are in warranty for customer, but out of warranty for us to Honeywell.

Ready For quote

Repair Complete Signed

CGreen 24-10-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37136	Oxygen Sensor	0110042	V101751	Yes
SRN37137	Oxygen Sensor	0110042	V101762	Yes

mm 0140013 × 2 FOC mm 03/Ns, 585, SEN's

O110042 × 2 FOC New SIN'S SRS SRN'S

EXW - Ship with next order Add note to Acc to State Unin og 24-10-24