

Service Repair Sheet 68922

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

21/Oct/2024

Robert Connor

Repair Ref S/N
SRN37136 0110042 V101751

Equipment Type
Oxygen Sensor

Under Warranty

Parts Replaced

Qty: 1 0110042

Time :0 Hour(s)

Replaced under warranty with S/N V101779.

Repair Ref S/N
SRN37137 0110042 V101762

Equipment Type
Oxygen Sensor

Under Warranty

Parts Replaced

Qty: 1 0110042

Time :0 Hour(s)

Replaced under warranty with S/N V101780.