Service Repair Sheet SRS68918

Contact Name

Company/ Hospital Name

Department Position

Direct Phone

General Phone Opera Account

Email

Order Number

Date Received Booked in By

Main Company

Type Return

Andrew Smith

Golden Jubilee National Hospital

0141 951 5950 00008012

andrew.smith@gjnh.scot.nhs.uk

09/Oct/2024 Robert Connor

Viamed

Quote

Notes 03/Oct/2024 Steve Hardaker 03/Oct/2024 Steve Hardaker

Returning a VM-2500-S displaying device defective error for repair. Provide quote.

09/Oct/2024 Robert Connor

Received 1 x VM-2500-S s/n A1608130010, with silicone cover v2.

Ready For quote

Careen 11-10-24

Repair Complete Signed

CGNOON 29.10.24

| SRN      | Equipment  | Stock Ref | Serial Number | Warranty |
|----------|------------|-----------|---------------|----------|
| SRN37129 | Capnograph | 4410520   | A1608130010   | 2        |

4440000 0.5hr 2 E90 per hr. SIN, SRS, SRN

4430201 e15

SES, SEN

UPS XI EIZ

| Goods In Only<br>Decontamination<br>certificate provided<br>by customer |      |
|---|------|
| Cleaned by Viamed, if no declaration certificate from customer Signed:  | 2    |
| Goods Out Only<br>Cleaned by Viamed be                                  | fore |

Signed: Date: