

Service Repair Sheet 68931

Contact Name

Company/ Hospital Name

Direct Phone

Opera Account

Email

Date Received

Booked in By

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

06/Nov/2024

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN37184

0110429

JL55299066

Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N KG96499120.