

Viamed Limited - 15 Station Road - Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68940

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone

Opera Account

Email

Date Received

Booked in By

Mark Evans

Royal United Hospitals Bath

Medical Equipment Management Service

Senior Clinical Technologist

01225824140 01225428331

00000350

mark.evans7@nhs.net

12/Nov/2024 Robert Connor

Repair Ref S/N SRN37187 0110452 HH82199042 Equipment Type Oxygen Sensor

Under Warranty

Time: 0 Hour(s)

Parts Replaced

0110452 Qty: 1

Replaced under warranty with S/N KH66499134