

Vidilied Lilling Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68855

Contact Name

Company/ Hospital Name

Department Position **Direct Phone** General Phone Opera Account

Email

Order Number

Date Received Booked in By

Atif Hussain

Luton & Dunstable Hospital Clinical Engineering Department Theatre Equipment Manager 01582491166 ext 2480

01582497042

00003490

atif.hussain@ldh.nhs.uk

30138975 29/Jul/2024 Robert Connor

Repair SRN36564 Ref

S/N 4410520 A1711160006 **Equipment Type**

Capnograph

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

4420504 Qty: 1

The Capnograph VM 2500-S has been repaired. The ISA module has been replaced. The unit has been tested and working as expected.