

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68964

Contact Name

Company/ Hospital Name **Direct Phone**

General Phone Opera Account

Email

Order Number

Date Received Booked in By

Tim Bray

Medisafe Ltd 01962762098

01962885777 00011608

tim.bray@medisafe.org.uk

5991

20/Nov/2024

Robert Connor

Repair SRN37464 Ref S/N

1410000 PR0490A19A

Equipment Type Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

The unit didn't turn on.

I have replaced the broken power lead and the transducer interface cushion.

The calibration has been checked and a new calibration certificate issued.

14