Forth Valley Medical Physics Department Forth Valley Royal Hospital Larbert FK5 4WR



Date: Tuesday, 19 November 2024

Tel: 01324-566-953

Email: arlene.gallagher@nhs.scot

Dear Sir/Madam,

Please find enclosed the following item for repair/service/calibration. Item: V1000

Equipment No.: 210425

Serial No.: PR01985A11

Fault: Annual calibration due

If the work required is not covered under warranty or by a service contract please email

Please provide a service report when the item is returned. Yours faithfully,

Arlene Gallagher