

Service Repair Sheet 68967

Contact Name

Company/ Hospital Name

Department

Position

General Phone

Opera Account

Email

Date Received

Booked in By

Derek Smith

Vet Direct Services Ltd

Repairs Department

Technical Support Co-Ordinator

0191 2642705

00012824

[derek.smith@vet-direct.com](mailto:derek.smith@vet-direct.com)

27/Nov/2024

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37465	0111275	A106115	Oxygen Analyser	Complete - Repaired Time :0 Hour(s)

The device was reading 77.3 minimum in air.

I have performed a reset and checked the oxygen sensor is in spec.

Repair	Ref	S/N	Equipment Type	
SRN37466	0110660	A110814	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.