



Service Repair Sheet 68938

Contact Name

Filipe

Company/ Hospital Name

Gama Aviation Plc

Direct Phone

01252553029

General Phone

01252 553029

Opera Account

CID19740

Email

medical@gamaaviation.com

Date Received

28/Oct/2024

Booked in By

Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN37141	0310291	FA56833001	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380060

Qty: 1 0121318

Qty: 1 0339950

The Maxblend 2 FA56833001 has been performance and calibration checked.

The damaged front cover has been replaced and an external power supply has been supplied as requested.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37142	0110452	HH82199025	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.