

## Service Repair Sheet SRS68938

Contact Name Filipe  
 Company/ Hospital Name Gama Aviation Plc  
 Department  
 Position  
 Direct Phone 01252553029  
 General Phone 01252 553029  
 Opera Account CID19740  
 Email medical@gamaaviation.com  
 Order Number  
 Date Received 28/Oct/2024  
 Booked in By Robert Connor  
 Main Company Viamed  
 Type Return Quote

## VIAMEDclean

Goods In Only  
 Decontamination  
 certificate provided  
 by customer ☒

Cleaned by Viamed,  
 if no declaration certificate  
 from customer ☒  
 Signed: RG  
 Date: 28/10/24

Goods Out Only  
 Cleaned by Viamed before  
 returning to customer  
 Signed: \_\_\_\_\_  
 Date: \_\_\_\_\_

Notes 24/Oct/2024 Aqib Majeed

24/Oct/2024 Aqib Majeed

Customer is returning a Maxblend 2 Low flow Air/oxygen Blender SN FA56833001 for annual performance check

24/Oct/2024 Aqib Majeed

Also requires a new charger on the quote as one in the device is broken

28/Oct/2024 Robert Connor

Received 1 x MaxBlend2 s/n FA56833001, with MAX550E s/n HH82199025, blender flow diverter, blender nip, and pole/rail mounting clamp. Front bezel of blender is cracked, and mounting plate on clamp is loose due to missing screw.

Ready For quote

C Green 30.10.24

Repair Complete Signed

C Green 5.12.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37141	Blender	0310291	FA56833001	N
SRN37142	Oxygen Sensor	0110452	HH82199025	Yes

0380060 x 1 @ £90  
 S/N, SRS, SRN

0121318 x 1 @ £52.50  
 SRS, SRN

0339950 x 1 @ £60  
 SRS, SRN

\* 0140011 x 1 FOC  
 S/N, SRS, SRN

→ I missed off 1st copy  
 of 6.12.24.

UPS x 1 @ £12.