

Service Repair Sheet SRS68966

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Hussein Remtulla
St James University Hospital
Clinical Engineering
Medical Electronics Technician
01132066882
01132433144
00002570
hussein.remtulla@nhs.net

28/Nov/2024
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 26/Nov/2024 Aqib Majeed

26/Nov/2024 Aqib Majeed

customer is returning 3 x AX300 Oxygen Monitors, S/N s are 333728, 261265 and 240356.

333728 - Damaged screen

261265 - Not switching on

240356 - Battery Connector broken sensor connector lose.

28/Nov/2024 Robert Connor

3 x AX300i s/n 333728, 240656, no s/n on third unit, but reportedly is 261265. 333728 has a cracked screen.

Ready For quote

CGNORN 10-12-24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37472	Oxygen Analyser	0111230	333728	222
SRN37473	Oxygen Analyser	0111230	240656	
SRN37474	Oxygen Analyser	0111230	261265	

0140004 x 0.5hr @ £90 = £45
S/N, SRS, SEN

0131215 x 1 @ £3
SRS, SEN

0121216 x 1 @ £45
SRS, SEN

UPS x 1 £12