

Service Repair Sheet SRS68979

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Derek Smith

Vet Direct Services Ltd

Repairs Department

Technical Support Co-Ordinator

0191 2642705

00012824

derek.smith@vet-direct.com

09/Dec/2024

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒Cleaned by Viamed,
if no declaration certificate
from customer ☒Signed: RSDate: 9/12/24

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 09/Dec/2024 Robert Connor

09/Dec/2024 Robert Connor

Received 1 x OxiQuant S s/n A106106, with OOI103 s/n A110805, flow diverter, blue tee, and oxygen stem.

09/Dec/2024 Robert Connor

Unable to calibrate, unit previously repaired on SRS68894, reset unit and replaced keypad membrane 18/9/24.

Ready For quote

CGreen 12.12.24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37490	Oxygen Analyser	0111275	A106106	Yes
SRN37491	Oxygen Sensor	0110660	A110805	N

3 Part of unit.

0140137 x 1 FOC

S/N, SRS, SRN

- include the details of the
sensor as well.

CG 12.12.24

UPS x 1 FOC.