

Service Repair Sheet SRS68979

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Derek Smith
Vet Direct Services Ltd
Repairs Department
Technical Support Co-Ordinator

0191 2642705
00012824
derek.smith@vet-direct.com

09/Dec/2024
Robert Connor
Viamed
Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒
Signed: RS
Date: 9/12/24

Goods Out Only

Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 09/Dec/2024 Robert Connor
09/Dec/2024 Robert Connor
Received 1 x OxiQuant S s/n A106106, with OOI103 s/n A110805, flow diverter, blue tee, and oxygen stem.
09/Dec/2024 Robert Connor
Unable to calibrate, unit previously repaired on SRS68894, reset unit and replaced keypad membrane 18/9/24.

Ready For quote

ECgreen 12.12.24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37490	Oxygen Analyser	0111275	A106106	Yes
SRN37491	Oxygen Sensor	0110660	A110805	N

3 Part of Unit.

0140137 x 1 FOC
S/N, SRS, SRN
(include the details of the sensor as well.)
cg 12.12.24

Remove
cg 13.12.24

~~UPS x 1 FOC.~~

Add

0140015 x 1 FOC ← SRN37941
old S/N, SRS, SRN

0110660 x 1 @ E72.
New S/N, SRS, SRN.

UPS x 1 FOC.