

Equipment Sent To Supplier

Job Reference :	598264/3	Date :	10/12/2024
-----------------	----------	--------	------------

Equipment Details

Asset Number : M83595 & M83594
Serial Number : 040463/040464
Description : Tom Thumb
Department : Birth Centre
Fault/Additional Info : Service

Action Required

* Please select as appropriate.

Please find enclosed the above unit requiring repair/service as previously discussed.

- ☐ These units are covered for repair through a previous agreement.
☐ We believe this unit to be under warranty. The unit was purchased on «PurchaseDate» .
☒ This has been discussed with your company previously and a fixed price repair of £ has been agreed. Please use order number .

Declaration

Is the Item contaminated? YES Or No No

Type Of Contamination:

Has the Item been decontaminated? YES or No Yes

This equipment has been decontaminated in accordance with the Trusts Equipment Decontamination Policy.

Decontamination Method used: CliniWipe

Signed :T Holland

Date: 10-12-24

If unit is not covered under contract/warranty, then It would be grateful if a quotation for the repair could be forwarded to enable generation of a Purchase Order.

If you have any queries relating to this matter, please do not hesitate to contact me.

Kind Regards
«Technician»

Return Address

EBME
North Manchester General Hospital
Delaunays Road
M8 5RB

*Please cc EBME.TechnicalNMGH@mft.nhs.uk in any email correspondence
Telephone : 0161 720 2347