

Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68977

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone

Opera Account

Email

Order Number Date Received Booked in By

Kamal Pacitti

North Middlesex University Hospital Clinical Engineering Department Specialist Clinical Engineer

02088873790 02088872000 00003070

kamal.pacitti@nhs.net

NMU598191 16/Dec/2024 Robert Connor

Repair SRN37535 0310200 BX1854643

Ref

S/N

**Equipment Type** Blender

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

0332001 Qty: 1 0380019

Blender BX1854643 has been stripped and cleaned. All O rings, diaphragms etc have been replaced and it has been calibrated.