



VIAMED

Cathy Green

Viamed Limited - 15 Station Road - Cross Hills
Keighley - West Yorkshire - BD20 7DT - United Kingdom
Tel: +44 (0)1535 634 542 - Fax: +44 (0)1535 635 582
Email: info@viamed.co.uk Website: www.viamed.co.uk



Service Repair Sheet 68979

Contact Name

Company/ Hospital Name

Department

Position

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Derek Smith

Vet Direct Services Ltd

Repairs Department

Technical Support Co-Ordinator

0191 2642705

00012824

derek.smith@vet-direct.com

151416

09/Dec/2024

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37490	0111275	A106106	Oxygen Analyser	No Fault Found Time :0 Hour(s)

Tested with a good sensor, the OxiQuant S is no fault found.

Repair	Ref	S/N	Equipment Type	
SRN37491	0110660	A110805	Oxygen Sensor	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0110660

The sensor had reached the end of it's life. Replaced with S/N A111623.