

Service Repair Sheet SRS68966

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sam Holmes

Hussein Remtulla

St James University Hospital

Clinical Engineering

Medical Electronics Technician

01132066882

01132433144

00002570

hussein.remtulla@nhs.net

28/Nov/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 26/Nov/2024 Aqib Majeed

26/Nov/2024 Aqib Majeed

customer is returning 3 x AX300 Oxygen Monitors, S/N s are 333728, 261265 and 240356.

333728 - Damaged screen

261265 - Not switching on

240356 - Battery Connector broken sensor connector lose.

28/Nov/2024 Robert Connor

3 x AX300i s/n 333728, 240656, no s/n on third unit, but reportedly is 261265. 333728 has a cracked screen.

Ready For quote

CGreen 10-12-24

Repair Complete Signed

CGreen 8-1-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37472	Oxygen Analyser	0111230	333728	2
SRN37473	Oxygen Analyser	0111230	240656	2
SRN37474	Oxygen Analyser	0111230	261265	2

unable to repair

repaired

unable to repair

0140004 x 0.5hr @ £90 = £45
S/N, SRS, SEN

0131215 x 1 @ £3
SRS, SEN

0121216 x 1 @ £45
SRS, SEN

UPS x 1 £12

Please Add:

0180004

~~0140004~~ x 2 FOC

unable to be repaired

Customer requested to units to
be returned.

S/N 333728, 261265
333728, 37472, 37474