Wé

## North Middlesex University Hospital NHS Trust

## North Middlesex University Hospital

Clinical Engineering Main Building Floor Level [-1] Sterling Way, London N18 1QX Email: kamal.pacitti@nhs.net Tel: 020 88872582

Date of dispatch: 08/01/2025

o: Viamed	Ltd. Our WO#: 124886, 124884
5 Station Ro	oad
Cross Hills, K	Ceighley
BD20 7DT	
Contact Nan	ne: Service Dept
	steve.hardaker@viamed.co.uk
Tel: +44 (0):	1535 634542
Dear Service	
Please find	enclosed equipment X2 IHC2003 Blenders ref SRS68983,
Serial No:	BX1854180, BX1854201
order num	
Fault desc	ription: needs overhauling.
DECONTA	AMINATION (Please tick one)
A)	This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
m)	The equipment may be contaminated by potentially infected material
В)	(eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
C)	The equipment may be contaminated with potentially infected material
	(eg. Blood/body fluids) but could not be decontaminated.
Contam	ninated/potentially hazardous equipment must be despatched in a sealed container/bag
TRANS	PORT/COURIERS NAME: TNT
	PRINT:
	SIGN: