

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68969

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone Opera Account

Email

10

Zinc

100

Rece Soc

2 V

h Bi

Order Number **Date Received** Booked in By

David Watson

Darlington Memorial Hospital Clinical Engineering Department Clinical Engineering Technician

01325743048 01325380100 00001350

david.watson28@nhs.net

CDD0006203288 09/Dec/2024 Robert Connor

Repair SRN37489 Ref

S/N 0310030 VMDI14 **Equipment Type** Tom Thumb

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

0380000 Qty: 1

Tom Thumb TT480 VMDI14 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.