

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68974

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone

Opera Account

Email Order Number

Date Received Booked in By

Tim Holland

North Manchester General Hospital

Clinical Engineering Dept. Senior Biomedical Engineer

01617202347 01617954567 00003580

timothy.holland@mft.nhs.uk

000487407 16/Dec/2024 Robert Connor

Repair

Ref S/N SRN37536 0310030 040463 Equipment Type Tom Thumb

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 040463 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Ref S/N SRN37537 0310030 040464

Equipment Type Tom Thumb

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1 0380000

Tom Thumb TT480 040464 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.