

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68995

Contact Name

Company/ Hospital Name

Department Position **Direct Phone** General Phone Opera Account

Email

Date Received Booked in By

Donna Kelly

Bradford Royal Infirmary Clinical Engineering Admin Assistant 01274364147 01274542200 00000620

donna.kelly2@bthft.nhs.uk

09/Jan/2025 Robert Connor

Repair SRN37558

Ref

S/N

1410000 PR03485A10

Equipment Type

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1

1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.