

# Service Repair Sheet SRS68997

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Harroop Sarai

Escatec Mechatronics Ltd

Operations Buyer

01455555500

01455555500

00013052

Harroop.Sarai@jjsmanufacturing.co.uk

16/Jan/2025

Robert Connor

Viamed

Warranty

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☒

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 10/Jan/2025 Steve Hardaker

10/Jan/2025 Steve Hardaker

Returning a 0110432 Max-250(B) under warranty, s/n KF69099174.

Fault is "The O2 sensor, output not changing with input", which suggests non-linear.

16/Jan/2025 Robert Connor

Received 1 x MAX-250B s/n KF69099174

Ready For quote

Repair Complete Signed

C. NEEN 20.1.25.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37581	Oxygen Sensor	0110432	KF69099174	Yes

0140013 x 1 FOC  
old S/N, SRS, SRN

0110432 x 1 FOC  
New S/N, SRS, SRN

UPS x 1 FOC