

KG Full, DL Full



Ocean Spirit Scuba Diving Mauritius

 **CID19623 Opera CID19623 Type:Vandagraph Retail**
Ocean Spirit Scuba Diving Mauritius Coastal Road, ,
Pereybere, , 20234, Mauritius
Tel **59052479** GBP Retail Price List Vandagraph (0010)
[Log Call](#) [Add Issue](#)
Proforma Credit Limit 0.00GBP

- [Account Home](#) [Main Details](#) [Account Memos](#) [Sales History](#) [Stock References](#) [Cust./Supp. Returns](#) [Service Visits](#) [Distributor Agreements](#)
- [Documents Files](#) [Linked Issues](#) [Regulatory Agreements](#)

SRS68986

SRS Created : 02 Jan 2025
Created By Ryan Swaine
Add Watch

- [Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
Add Items to Supplier Returns Box

[Add](#)

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Linked to Order Reference  **154594**

Service Repair Sheet 68986		Notes
Company / Hospital	Ocean Spirit Scuba Diving Mauritius	
Contact Name	Jill Holloway	02/Jan/2025 Ryan Swaine
Department		02/Jan/2025 Ryan Swaine
Position		2x O2 analysers for repair.
Company Phone	59052479	09/Jan/2025 Robert Connor
Direct Phone	59052479	Received 2 x tek-ox s/n TX2294, TX4077
Opera Account	CID19623	
Email	jill4949@gmail.com	LINKED ISSUE NOTES:
Order Number		352642 :
Viamed ORD Number		AutoGenerated Issue SRS68986 Appears to be Complete
Date Received Into building	09 Jan 2025	
Type	Quote Before Repair Move to Repair	17 Jan 2025 Catherine Spence Vandagraph repair, still with vandagraph
		17 Jan 2025 Catherine Spence

Issues?

352642

Items for Repair

... ..

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37559	Vandagraph Tek Ox	7910211 Requires Service Manual Linking in System	 967027	TX2294	Oxygen Analyser Tek-Ox	No	No	Written Off 15 Jan 2025 Michael Green	Multiple faults	00:00
SRN37559 Engineer Notes: INTERNAL NOTES not for customer discussion 10/Jan/2025 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. All connectors have corrosion. The PCB does power up, but gives false readings. The R-17VAN Oxygen sensor has corrosion around the connector. 15/Jan/2025 Michael Green As requested, the unit has been written off.										
SRN37560	Vandagraph Tek Ox	7910201 Requires Service Manual Linking in System	 2179556	TX4077	NM-Argon Analyzer	Yes	No	Complete - Repaired 15 Jan 2025 Michael Green	Battery Contacts	00:00
SRN37560 Engineer Notes: INTERNAL NOTES not for customer discussion 10/Jan/2025 Michael Green The Tek-Ox analyser has been tested. The unit is working. There is some corrosion to the battery door contact. The R-17VAN Oxygen sensor has been tested in air and Oxygen. 15/Jan/2025 Michael Green The Tek-Ox analyser has been repaired. The battery door contact has been replaced. New batteries have been fitted. The R-17VAN Oxygen sensor has been tested in air and Oxygen.										

Currently Viewing ITEM SRN37559 Vandagraph Tek Ox 7910201 TX4077 NM-Argon Analyzer

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The battery door contact has been replaced. New batteries have been fitted. The R-17VAN Oxygen sensor has been tested in air and Oxygen.	10/Jan/2025 Michael Green The Tek-Ox analyser has been tested. The unit is working. There is some corrosion to the battery door contact. The R-17VAN Oxygen sensor has been tested in air and Oxygen. 15/Jan/2025 Michael Green The Tek-Ox analyser has been repaired. The battery door contact has been replaced. New batteries have been fitted. The R-17VAN Oxygen sensor has been tested in air and Oxygen.	The Tek-Ox analyser has been repaired. The battery door contact has been replaced. New batteries have been fitted. The R-17VAN Oxygen sensor has been tested in air and Oxygen.

ISO REVIEW

Please Select

Instructions