

Viamed Limited - 15 Station Road - Cross Hills Keighley - West Yorkshire - BD20 7DT - United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68983

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone Opera Account

Email

Order Number

Date Received Booked in By

Kamal Pacitti

North Middlesex University Hospital Clinical Engineering Department Specialist Clinical Engineer

02088873790 02088872000

00003070

kamal.pacitti@nhs.net

RFL602746 14/Jan/2025 Robert Connor

Repair

Ref S/N

SRN37573 0310200 BX1854180

Equipment Type Blender

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 0332001 Qty: 1 0380019

Blender BX1854180 has been stripped and cleaned. All O rings, diaphragms etc have been replaced and it has been calibrated.

S/N SRN37574 0310200 BX1854201 Equipment Type

Blender

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 0332001 0380019 Qty: 1

Blender BX1854201 has been stripped and cleaned. All O rings, diaphragms etc have been replaced and it has been calibrated.