

Service Repair Sheet 68987

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Manuela Kellner

Hellmut Habel Ges.m.b.H (EURO)

431292664228

004312926642

00006343

Manuela.Kellner@habel-medizintechnik.at

14/Jan/2025

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN37579	1410000	PR02315A11	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
