

Service Repair Sheet 68950

Contact Name	Brett Thorpe
Company/ Hospital Name	Nautilus
Direct Phone	0333 444 0104
General Phone	0333 4440104
Opera Account	CID17057
Email	info@nautilus.uk
Date Received	11/Nov/2024
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37185		1	Vandagraph Tek Ox	No Fault Found Time :1 Hour(s)

The Tek-Ox analyser has been tested and given an internal inspection. The described fault could not be reproduced. As a precaution the internal connectors have been cleaned. The batteries have been replaced.

The supplied R-17VAN Oxygen sensor (SN:108091 C3) has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37186		2	Vandagraph Tek Ox	No Fault Found Time :1 Hour(s)

The Tek-Ox analyser has been tested and given an internal inspection. The described fault could not be reproduced. As a precaution the internal connectors have been cleaned. The batteries have been replaced. Some missing case screws have been replaced.
