

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 - Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 69002

Contact Name

Company/ Hospital Name

Department Position Direct Phone

General Phone Opera Account

Email

Date Received Booked in By

Paul James

Coventry University Hospital

EBME Department Electronics Engineer

02476968367 02476968367 00001288

paul.james@uhcw.nhs.uk

23/Jan/2025 Robert Connor

Repair

Ref

S/N SRN37592 1410000 PR01713A10

Equipment Type Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.