

## Equipment Sent To Supplier

Reference :	601196 601195	Date :	28/01/2025
-------------	---------------	--------	------------

### Equipment Details

Asset Number	: M83600 & M83595
Serial Number	: 040466 040463
Description	: Viamed - TT480 - RESUSCITATION AID
Department	: BIRTH CENTRE
Fault/Additional Info	: PM - PEEP not going until 15LPm

### Action Required

\* Please select as appropriate.

Please find enclosed the above unit requiring repair/service as previously discussed.

- ☐ These units are covered for repair through a previous agreement.
- ☐ We believe this unit to be under warranty. The unit was purchased on ?? .
- ☐ This has been discussed with your company previously and a fixed price repair of £                      has been agreed. Please use order number .

### Declaration

Is the Item contaminated?                      YES Or No                      no

Type Of Contamination:

Has the Item been decontaminated?                      YES or No                      yes

*This equipment has been decontaminated in accordance with the Trusts Equipment Decontamination Policy.*

Decontamination Method used:

Signed :T Holland

Date: 28-1-25

If unit is not covered under contract/warranty, then It would be grateful if a quotation for the repair could be forwarded to enable generation of a Purchase Order.

If you have any queries relating to this matter, please do not hesitate to contact me.

Kind Regards

**Tim Holland**

### Return Address

**EBME**

**North Manchester General Hospital**

**Delaunays Road**

**M8 5RB**

\*Please cc EBME.TechnicalNMGH@mft.nhs.uk in any email correspondence

Telephone : 0161 720 2347