

Service Repair Sheet 68982

Contact Name	Paul Burrows
Company/ Hospital Name	Nottingham University Hospital ( Queens Medical Centre Campus)
Department	Medical Equipment Services unit (MESU)
Position	Clinical Engineering Technologist
General Phone	01159249924
Opera Account	00003930
Email	paul.burrows5@nhs.net
Order Number	202011432
Date Received	06/Jan/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN37545	5610152	AL000078	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	0380050
Qty: 1	0332004

Blender AL000078 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.

Repair	Ref	S/N	Equipment Type	
SRN37546	5610152	AL000107	Blender	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	0380050
Qty: 1	0332004

Blender AL000107 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.