

Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 69008

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone Opera Account

Email

Repair

SRN37591

Date Received

Booked in By

Ref S/N

1410000 PR03485A16

116

Sarah Fairley

01384456111

01384456111 00001465

23/Jan/2025 Robert Connor

Russells Hall Hospital

Secretary/Administrator

sarah.fairley2@nhs.net

Medical Engineering Department

Equipment Type Foetal Simulator

Complete - Repaired Time :0 Hour(s)

Under Warranty

Parts Replaced

Qty: 1 1480000 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.