

Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 69017

Contact Name

A D Wharton

Company/ Hospital Name

North Cumbria University Hospitals NHS Trust 01228 523444

General Phone Opera Account

00000980

Order Number Date Received

Booked in By

RNNN400255271 03/Feb/2025

Robert Connor

Repair

Ref S

S/N

Equipment Type

SRN37600 1410000 PR01225A15

Foetal Simulator

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1

1480000

Qty: 1

1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.