

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 69013

Contact Name

Company/ Hospital Name

Department Position **Direct Phone** General Phone

Opera Account Email

Order Number Date Received Booked in By

David Watson

Darlington Memorial Hospital Clinical Engineering Department Clinical Engineering Technician

01325743048 01325380100 00001350

david.watson28@nhs.net

CDD0006250621 06/Feb/2025 Robert Connor

Repair SRN37602 Ref

S/N 0310030 VMDI 11 **Equipment Type** Tom Thumb

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1

0380000

Tom Thumb TT480 VMDI11 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair SRN37603 Ref

S/N 0310030 VMDI12 Equipment Type Tom Thumb

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1

0380000

Tom Thumb TT480 VMDI12 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.

Repair SRN37604 Ref

S/N 0310030 vmbc15

Equipment Type Tom Thumb

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1

0380000

Tom Thumb TT480 VMBC15 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.