Service Repair Sheet SRS69005

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

**Debbie Summers** 

Elham Valley Referrals

Head Veterinary Nurse

01303 840499

01303 8490499

00012494

debbie@elhamvalley.com

20/Jan/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination certificate provided by customer

Cleaned by Viamed, if no declaration certificate from customer

Signed: \_ Date:

Goods Out Only

Cleaned by Viamed before returning to customer

Signed:

Date:

Notes 20/Jan/2025 Robert Connor

20/Jan/2025 Robert Connor

Customer has returned 1 x DB3 s/n M0005639, with patient lead and 9V battery. Requested fixed price repair and replacement patient lead p/n 2520000.

Ready For quote

Repair Complete Signed

CGNOON 5.2.25

career 21.2.25.

SRN	Equipment	Stock Ref	Serial Number	Warranty
	Microstim DB3	2510011	M0005639	2

2540010 ×1 0 £65. 5/N, SRS, SRN

2520000 & E18-50. as per costomer letter. Ups  $\times$  1 @ E12.