

3K369040

## Repair Quotation Request

Date of request: 20/02/2025



**Oxford University Hospitals**  
NHS Foundation Trust

**Post to:**

Viamed Ltd  
15 Station Road  
Cross Hills  
Keighley  
BD20 7DT

**Deliver To:**

Clinical Engineering  
Industrial Block  
John Radcliffe Hospital  
Headley Way  
OX3 9DU

**Telephone:** 01865 221548

**Email:** [Clinical.engineering@ouh.nhs.uk](mailto:Clinical.engineering@ouh.nhs.uk)

The following item(s) of equipment are reported faulty and require testing/repair.

**Brand:** VIAMED

**Model:** MICROSTIM DB3

**Serial No:** H0003026

**Asset No:** 081689

**The reported fault:**

Missing cable and faulty control knob.

Please carry-out an evaluation and forward a quotation to Clinical Engineering at the following address: [Clinical.engineering@ouh.nhs.uk](mailto:Clinical.engineering@ouh.nhs.uk)

Please include the **Job reference 698555** in all quotes and correspondence related to this request.

Kind regards,

Clinical Engineering