

Service Repair Sheet 69020

Contact Name	Katy Romanowski
Company/ Hospital Name	Tenacore LLC
Direct Phone	8002972241
General Phone	(800) 297-2241
Opera Account	00007996
Email	Katy.Romanowski@tenacore.com
Date Received	17/Feb/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN37620	1410000	PR01807A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.
