

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Steven Byrne
John Radcliffe Hospital
Clinical Engineering
Senior Clinical Technologist
01865221548
01865741166
00004040
Steven.Byrne@ouh.nhs.uk

25/Feb/2025
Robert Connor
Viamed
Warranty

VIAMEDclean	
Goods In Only Decontamination certificate provided by customer	<input checked="" type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 20/Jan/2025 Kate Griffiths

20/Jan/2025 Kate Griffiths

Will send in a faulty nR-47v, s/n V107418. Under warranty

20/Jan/2025 Kate Griffiths

Reply re fault: we use them in the Fabian vents, this cell brings up the error message "O2 sensor defect". I tried it in a different vent and got the same error message. Address to return it to: Steven Byrne, Neonatal unit (Clinical Engineering), John Radcliffe Hospital, Headley Way, Headington Oxford, OX3 9DU

25/Feb/2025 Robert Connor

Received 1 x R47v s/n V107418, packaging arrived damaged by Royal Mail who lied about it being damaged when entering the country.

Ready For quote

Repair Complete Signed

CGreen 3.3.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37627	Oxygen Sensor	0110047	V107418	Yes

0140013 x 1 FOC
S/N, SRS, SRN

0110047 x 1 FOC
New S/N, SRS, SRN
Packaged