## North Middlesex University Hospital NHS

North Middlesex University Hospital

Clinical Engineering Main Building Floor Level [-1] Sterling Way, London N18 1QX Email: kamal.pacitti@nhs.net

Tel: 020 88872582

Date of dispatch: 26/02/2025

Our WO#: 124952, 123824 and 123979

To: Viam	ed Ltd.
15 Station	Road
Cross Hills	s, Keighley
BD20 7D7	
	lame: Service Dept
E-mail:	steve.hardaker@viamed.co.uk
Tel: +44 (	0)1535 634542

Dear Service Dept

X2 IHC2003 Blenders ref SRS69043 Please find enclosed equipment

Serial No: BX1854178, BX1854179 and BX1854640

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

needs overhauling. Fault description:

## **DECONTAMINATION** (Please tick one)

- This equipment is NOT as far as I am aware contaminated by any potentially infected A) material (eg. Blood/body fluids)
- The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with B) the North Middlesex Hospital trust Policy.
- The equipment may be contaminated with potentially infected material C) (eg. Blood/body fluids) but could not be decontaminated.

Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag

TRANSPORT/COURIERS NAME:	TNT	
PRINT:		
SIGN:		