

Service Repair Sheet SRS69044

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mark Phipps

Smit Mobile Equipment

Mobile Medical Field Service

Service Manager

0127664490

0127664490

00020025

mark.phipps@smit.eu

25/Feb/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC

Date: 23/2/25

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 24/Feb/2025 Kate Griffiths

24/Feb/2025 Kate Griffiths

3 x MX300 for repair - s/n 287917, 331755 and 247391. Customer not able to say what faults are

25/Feb/2025 Robert Connor

Received 3 x MX300i s/n 247391, 287917, 331755, with 3 x coiled cable s/n 0000003, 0004767, 0010575.

Ready For quote

CQueen 5.3.25

Repair Complete Signed

f31-50
GBP
Dist

SRN	Equipment	Stock Ref	Serial Number	Warranty
✓ SRN37646	Oxygen Monitor	0111235	247391	2
✓ SRN37647	Oxygen Monitor	0111235	287917	2
✓ SRN37648	Oxygen Monitor	0111235	331755	2
✓ SRN37649	Misc. Cable	0131202	0000003	2
SRN37650	Misc. Cable	0131202	0004767	2
SRN37651	Misc. Cable	0131202	0010575	2

✓ 0140005 x 1 @ 0.5hr @ £90 per hr
S/N, SRS, SRN

✓ 0131215 x 1 @ £2.40
SRS, SRN

✓ 0140005 x 1 @ 0.5hr @ £63 per hr
S/N, SRS, SRN

✓ 0121217 x 1 @ £46.20 changed to
0121217 @ 53.25
SRS, SRN

✓ 0140005 x 1 @ 0.5hr @ £63 per hr
S/N, SRS, SRN

✓ 0121208 x 1 @ £4.00
SRS, SRN.

→ 0140025 x 1 FCC.
S/N, SRS, SRN
0131202 x 1 £12.
S/N, SRS, SRN

UPS x 1 £12.00