

Service Repair Sheet 69052

|                        |                                     |
|------------------------|-------------------------------------|
| Contact Name           | Jeenu Maria Jose                    |
| Company/ Hospital Name | Dorset County Hospital              |
| Department             | Clinical Engineering Department     |
| Position               | Clinical Engineering Support Worker |
| Direct Phone           | 01305251150                         |
| General Phone          | 01305251150                         |
| Opera Account          | 00001430                            |
| Email                  | Jeenu.Jose@dchft.nhs.uk             |
| Date Received          | 10/Mar/2025                         |
| Booked in By           | Robert Connor                       |

---

|                |         |          |                  |  |
|----------------|---------|----------|------------------|--|
| Repair         | Ref     | S/N      | Equipment Type   |  |
| SRN37684       | 1410000 | PR065A18 | Foetal Simulator | Complete - Repaired<br>Time :0 Hour(s) |
| Parts Replaced |         |          |                  |  |
|                | Qty: 1  | 1480000  |                  |  |
|                | Qty: 1  | 1430309  |                  |  |

V1000 has had transducer interface cushion replaced and calibration has been checked.

---