Service Repair Sheet 69047

Contact Name Sudath Weeraman
Company/ Hospital Name Prime Lanka Associate

Direct Phone 9410718732285 Opera Account 00006714

Email sudathweeraman17@gmail.com

Date Received 13/Mar/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN37686 0110429 KH39399174 Oxygen Sensor

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N KH39399007.