

Service Repair Sheet SRS69044

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Mark Phipps
Smit Mobile Equipment
Mobile Medical Field Service
Service Manager
0127664490
0127664490
00020025
mark.phipps@smit.eu

25/Feb/2025
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒
Signed: RC
Date: 23/2/25

Goods Out Only

Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 24/Feb/2025 Kate Griffiths

24/Feb/2025 Kate Griffiths

3 x MX300 for repair - s/n 287917, 331755 and 247391. Customer not able to say what faults are

25/Feb/2025 Robert Connor

Received 3 x MX300i s/n 247391, 287917, 331755, with 3 x coiled cable s/n 0000003, 0004767, 0010575.

Ready For quote

CGreen 5.3.25

Repair Complete Signed

CGreen 17.3.25

f31-50
GBP
Dist

SRN	Equipment	Stock Ref	Serial Number	Warranty
☒ SRN37646	Oxygen Monitor	0111235	247391	2
☒ SRN37647	Oxygen Monitor	0111235	287917	2
☒ SRN37648	Oxygen Monitor	0111235	331755	2
☒ SRN37649	Misc. Cable	0131202	0000003	2
SRN37650	Misc. Cable	0131202	0004767	2
SRN37651	Misc. Cable	0131202	0010575	2

✓ 0140005 x 1 @ 0.5hr @ £90 per hr
S/N, SRS, SRN

✓ 0131215 x 1 @ £2.40
SRS, SRN

✓ 0140005 x 1 @ 0.5hr @ £63 per hr
S/N, SRS, SRN

✓ 0121217 x 1 @ £46.20 changed to
0121217 @ 53.25
SRS, SRN

✓ 0140005 x 1 @ 0.5hr @ £63 per hr
S/N, SRS, SRN

0121208 x 1 @ £4.00
SRS, SRN.

→ 0140025 x 1 fOC.
S/N, SRS, SRN
0131202 x 1 £12.
S/N, SRS, SRN

UPS x 1 £12.00