

Service Repair Sheet 69026

Contact Name	Mick Smithson
Company/ Hospital Name	Lamboo Medical (UK)
Position	Duty Manager
Direct Phone	0194 2724272
General Phone	01942 724 272
Opera Account	00013111
Email	Mick@lamboo-medical.com
Date Received	17/Feb/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37622	0111276	103629	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

The MySign O monitor has been tested. The unit is working as expected.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37623	0111276	103633	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

The MySign O monitor has been tested. The unit is working as expected.
