

Service Repair Sheet SRS69060

Contact Name

Sarah Johnston

Company/ Hospital Name

Brennan & Co NI

Department

Position

Direct Phone

02890410136

General Phone

02890410136

Opera Account

00012907

Email

sjohnston@brennanconi.com

Order Number

Date Received

17/Mar/2025

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC
Date: 17/03/25

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes Would like a monitor (she says and sensor) due for calib. S/N:HM50099074 - 0110452FA756990022 - ox monitor, unable to find in system/emails

10/Mar/2025 Kate Griffiths

Would like a monitor (she says and sensor) due for calib. S/N:

HM50099074 - 0110452

FA756990022 - ox monitor, unable to find in system/emails

17/Mar/2025 Robert Connor

Received 1 x MAXO2ME s/n FA75699022, with coiled cable 2209862, MAX550E s/n HH65699183

Ready For quote

CGreen 17.3.25

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37708	Oxygen Monitor	0111263	FA75699022	2
SRN37709	Misc. Cable	0131700	Tracking16	22
SRN37710	Oxygen Sensor	0110452	HH65699183	2

0180050 x 1
E33.75
S/N, SRS, SRN

0180020 x 1 @ E30
S/N, SRS, SRN.

0140012 x 1 FOC
Old S/N, SRS, SRN

0110452 x 1 E87.40
SRS SRN

UPS x 1 @ E8.20 3x 23x15x15cm